

Index: O 06

Corner: NW1/6
S20

LAND CORNER RECORD

State of Indiana
Hoosier National Forest

Polk F14

Twtnshp: 7N Range: 1E Section: 20 2nd P.M.

County: MONROE CO.

Polk_F14

EXISTING SURVEYS

Original Government Survey				Original Survey Evidence Found			
Year Surveyed:		By:		Date of Search:		By:	
Original Monument:				Monument Found:			
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance
Subsequent Corner Restoration				Evidence of Subsequent Corner Restoration Found			
Where Filed or Recorded:				Year Searched: By:			
Book: Page: Date:				Monument Found			
Monument Set:							
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance

OTHER EVIDENCE

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
The monument is located approximately 32' N72°W of the intersection of remnants of old fence running north-south and west, approximately 500' north from the intersection of Allens Creek Road and Rogers Road, at the northwest corner of a campground.	

PERPETUATION RECORD

Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position.			
Northwest 1/16 corner; A 2 1/2 inch aluminum monument with a 3 1/4 inch cap was set 0.3' above grade at the intersection of the lines formed from O05 to O07 and P06 to N06 (being the intersection of the lines formed from the North 1/16 between Section 19 and 20 to the Center North 1/16 and the Center West 1/16 to the West 1/16 corner between Section 17 and 20). A 1 inch iron pipe was found North 32 degrees WEST, 25.8' from the established corner. The origin of this monument is unknown. The intersection of remnants of old fence running north-south and west is North 54 degrees East, 20' from the established corner. A 1980 Forest Service reference card indicates the said pipe was found approximately 40' northwest of a fence corner. The said pipe is North 72 degrees West, 32' from the intersection of old fence remnants. To the East of said corner campers, sheds and other occupation is as much as 67' north of the established quarter-quarter line.			
Corner Diagram	Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.		
	12" Pin Oak N50°E 24.4' 10" Pignut Hickory N85°E 17.4' 20" Red Oak N55°W 23.0' <i>Referenced on BRG survey recorded as InstNo.2005011737.</i> <i>Accepted by the Monroe County Surveyor Review Board on August 6, 2019.</i>		
	Corner Recordation:	Certificate Prepared:	
	Filed and Recorded in County records:	Date:	
	Book:	Page:	
Section: 20	Geodetic Coordinates:	Lat./N.	Long./E.
	Edited By:	BTR	Date Created: 10/2004

Index:	O-6	Corner:	NW1/16	LAND CORNER RECORD				State of Indiana Hoosier National Forest
Twnshp:	7N	Range:	1E	Section:	20	2 nd P.M.	County	Monroe
EXISTING SURVEYS								
Original Government Survey					Original Survey Evidence Found			
Year Surveyed:		By:		Date of Search:		By:		
Original Monument:				Monument Found:				
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance	
Subsequent Corner Restoration					Evidence of Subsequent Corner Restoration Found			
Where Filed or Recorded:				Year Searched:	8/24/04	By:	B.Stone	
Book:	Page:	Date:		Monument Found	Rebar with an aluminum cap stamped as shown, set by Bledsoe, Tapp & Riggert Inc. flush with the ground with 3 large rocks placed around it.			
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance	

OTHER EVIDENCE

Describe corner loc. Relative to nearby features & dir. To corner location; note fences, roads, etc.	Sketch of Monument
Monument is located in a 30 foot diameter clearing. It is forested to the northeast, northwest and southwest. This monument is the northwest corner of the Sharwood Campground property. There are numerous encroachments. An aluminum survey marker post stands at the southeast edge of the monument. A 1" diameter 7" tall pipe next to a woodpile is N 26°W 26.1 feet from the monument. A white Dutchman camper is 27 feet southeast. A wooden 4" X 4" post with a water faucet and electric panel is S87°E 26.3 feet	

PERPETUATION RECORD

Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position.							
							
Corner Diagram		Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.					
		These trees are not tagged or marked: B. Oak (w/old east-west 22" wire in center) N 51°W 22.8 Ft. Hickory (w/wooden 19" squirrel feeder) S 45°E 22.5 Ft.					
		Corner Recordation:				Certificate Prepared:	
		Filed and Recorded in County records:				Date:	
		Book:				Page:	
Section:		20		Geodetic Coordinates:		Lat./N. Long./E. 	
		Edited By:		Robert J. Stone		Date Created:	
						8/30/04	


Index No. 016
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 7N. R. 1E. Mer. N.F. Hoosier County Monroe State Ind.
1/6 Corner common to sections 20 and _____

EXISTING SURVEYS	
Original Government Survey Year surveyed _____ Original monument _____ (Wood post, stone, pile of stones, pipe, etc.) Bearing Trees Species _____ Diameter _____ Bearing _____ Distance _____	Original Evidence Found Year of search _____ By _____ Monument found _____ Original Bearing Trees Found Species _____ Diameter _____ Bearing _____ Distance _____
Subsequent Corner Restoration Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ (Original, concrete post, iron rod, etc.) Bearing Trees, Reference Objects Species _____ Diameter _____ Bearing _____ Distance _____	Evidence of Subsequent Corner Restoration Found Year of search <u>1980</u> By <u>Tim Cummings</u> <u>Found pipe</u> Bearing Trees, Reference Objects _____ _____ _____ _____



Sketch

○ Corner ■ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Calvinized 1" pipe down in ground, app 40' Northwest of
fence corner. Fence from West and fence from North
tree line from South located app. 400' from North
up slope from jct. of Allen Creek road, Campground
to Southeast of pipe, white pine plantation to South
west.

Perpetuation Record

Monument and accessories established. Include brief description of area.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

At time of search:

1. Did you have the record description?
 Yes _____ No ✓

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc. _____

3. Mon hours spent in search 10 min.

4. Do you think additional search might
 recover evidence? Yes _____ No ✓

5. Signature Tim Cummings